

Response Marine, Inc.

Plaz Parts for Sound Marine- Dredge 30, HULL
 File: RMI\des\Sound\Dredge 30\
 revised: 10/17/08

Print Date: 10/17/08

3/16" Parts- 5083/86

<u>Part #</u>	<u>Pieces</u>	<u>Description</u>	<u>Bending</u>
F1	1	Frame 1	Y
F1U	2	Frame 1, Upper	Y
F2	1	Frame 2	Y
F-2U	2	Frame 2, upper	Y
F3	1	Frame 3, BHD	Y
F4	1	Frame 4	Y
F4U	2	Frame 4, Upper	Y
F5	1	Frame 5	Y
F5U	2	Frame 5, Upper	Y
F6	1	Frame 6	Y
F7	1	Frame 7	Y
F7-U	2	Frame 7, Upper	Y
TF	18	Filler/Doublers at Tees, for Frames	
TS-B	12	Filler/Doublers at Tees, for BHDS	
	47	Sub Total	

See dwg 317-B-1 for all Frame Bends
--

1/4" Parts- 5083/5086

<u>Part #</u>	<u>Pieces</u>	<u>Description</u>
B-AP	1	Bottom Plate, Fwd Port
B-AS	1	Bottom Plate, Fwd Stbd
B-BP	1	Bottom Plate, Aft Port
B-BS	1	Bottom Plate, Aft Stbd
BOW	1	Bow Sheer Guard
BOW-SG	1	Bow Sheer Guard
BS-1	2	Bottom Longitudinal 1 (fwd)
BS-2	2	Bottom Longitudinal 2 (fwd)
BS-3	2	Bottom Longitudinal 3 (fwd)
BS-4	2	Bottom Longitudinal 4 (fwd)
DM-A	2	Deck Margin, Fwd
DM-B	2	Deck Margin, Mid
DM-C	2	Deck Margin, Aft
SGD	2	Sheer Guard
TG	54	8"x6" Gussets for T/Frame
TRAN	1	Transom
TS-AP	1	Topsides, Fwd Port
TS-AS	1	Topsides, Fwd Stbd
TS-BP	1	Topsides, Aft Port
TS-BS	1	Topsides, Aft Stbd
TSL-A	2	Topside Stringer Fwd
TSL-B	2	Topside Stringer, Mid
TSL-C	2	Topside Stringer, Aft
	87	Sub Total

3/8" Parts, 5083/5086

<u>Part #</u>	<u>Pieces</u>	<u>Description</u>
BI	2	Bottom Insert (aft)
EG-A	2	Engine Girder Aft
EG-AA	2	Engine Girder Fwd
EG-AB	2	Engine Girder Aft
EG-B	2	Girder Flange
EG-C	2	Girder Flange
EG-D	2	Girder Flange

EG-E	2	Girder Flange
EG-F	2	Girder Flange
EG-G	2	Girder Flange
	20	Sub Total

1" Parts, 5083/5086

<u>Part #</u>	<u>Pieces</u>	<u>Description</u>
K-A	1	Keel, Fwd (MAY BE CUT AS A PATTERN ON OTHER STOCK)
K-B	1	Keel, Mid
K-C	1	Keel, Aft
K-D	1	Keel, Aft Vertical
	4	Sub Total
	158	Total Cut Parts



